

Hillsview

GOLF COURSE



Existing Clubhouse






Existing Interior






Existing Interior


Design Concepts



EXISTING S. F. = 3860
NEW S. F. = 3890
TOTAL = 7750 S. F.




EXISTING S. F. = 3860
NEW S. F. = 1790
TOTAL = 5650 S. F.



HILLSVIEW GOLF CLUBHOUSE

6-16-08



EXISTING SF	= 3880 SF
NEW	= 725 SF
TOTAL	= 4585 SF
PATIO	= 1115 SF
SEATING	= 82 SEATS

Construction Progress



Construction Progress



Construction Progress



Construction Progress




Construction Progress




Hillview Construction Schedule

Proposed- March 3, 2010



Total Financing Sources Golf Clubhouse Remodel Project



Total Estimated Project Cost = \$630,230



Thank You!